

AEROFLEET CATAMARAN

Belgium



Problem

Salt water, moisture, salty air. Surface outside: polyester. Surface inside: polyester and wood.

Solution

- Pre-treatment: degrease thoroughly, possibly sand
- System outside of the boat:
 Polyzinc + 1 layer Polyguard (protection of polyester)
 + antifouling
- System inside of the boat: Mixtane

MCUs can be applied in the most extreme conditions and were therefore chosen as the most suitable system.

Every year antifouling = system can resist for years.





